


Thermocouples

Transition Joint

With PTFE/PTFE
Cable



With FG/FG/SS
Braided Cable



Cable with Protective
SS Flex Hose



With Quick
Disconnect Connector



Protection Head & Mineral Insulated

Weather-Proof
Head



Flame-Proof
Head



Machine-Compacted
Mineral Insulated
Sheath



Ceramic Block
Termination



Application Specific

RCA Sheath for High Temperature



Ceramic Beaded for Muffle Furnace



Silicon Nitride Sheath for Casting



Triplex Multi-Level for Reactors



Bayonet Probes

Straight



L-Shape



Adjustable



Surface Probes

Washer Probe with SS Braided Cable



Washer Probe with PTFE/PTFE Cable



Non-Inmelt

