



► **Dimensions (mm)**




► **Wiring Instructions**



Wiring Diagram




Illustrative Wiring Connections



Earthing Selection

1. Use internal terminal marked "E" for grounding.
2. Use the screw provided on the outside of shell.

► **Installation & Mounting Holes**



Probe

1. Drill holes for probe insertion and flange mounting.
2. Install the flange and lock the screws.
3. Insert the probe and adjust the insertion length.
4. Lock the screw for gripping the probe.

Shell

5. Drill holes for mounting the shell.
6. Insert the plastic expansion pipe into the drilled holes.
7. Install the shell and fix the mounting screws