

Installation

Mounting

Figure 1





Figure 2



- 1 Tilt the unit and place the top mounting bracket over the DIN rail edge. Figure 1.
- 2 Press down to ensure the top hook is fully engaged. Figure 1.
- 3 Swing the bottom toward the rail and press until it snaps into place. Figure 2.

Un-mounting

Figure 1





Figure 2



- 1 Remove power supply male connector (3 pin) from its counter part. Figure 1.
- 2 Insert a flat-head screwdriver into the release tab slot. Figure 2.
- 3 Pull the screwdriver up to release the tension clip. Figure 2.
- 4 Swing the bottom out and lift the enclosure off the DIN rail. Figure 2.